



Stantec Consulting Services Inc.  
 30 Park Drive  
 Topsham ME U.S.A.  
 04086  
 Tel. 207.729.1199  
 Fax. 207.729.2715  
 www.stantec.com

**Stantec**

**Copyright Reserved**

The Contractor shall verify and be responsible for all dimensions. DO NOT scale the drawing - any errors or omissions shall be reported to Stantec without delay.  
 The Copyrights to all designs and drawings are the property of Stantec. Reproduction or use for any purpose other than that authorized by Stantec is forbidden.

**Consultants**

**Legend**

**NOTES**

- 1) COORDINATES SHOWN ARE ORIENTED TO THE MAINE COORDINATE SYSTEM OF 1983, EAST ZONE.
- 2) ELEVATIONS REFERENCE THE NORTH AMERICAN VERTICAL DATUM OF 1988.
- 3) POINTS LABELED "calc" ARE POINTS CREATED IN AUTOCAD FROM FIELD MEASUREMENTS.
- 4) THE SHAPES OF THE SPILLWAYS SHOWN HAVE BEEN SIMPLIFIED. THE GATES AND SLOTS FOR THE GATES WERE NOT MEASURED.
- 5) HIGH WATER LINE SHOWN IS THE "SCRUB LINE" OR LIMIT OF VEGETATION.

**LEGEND**

- ⊗ UTILITY POLE
- + ANCHOR
- LIGHT POLE
- OVERHEAD UTILITY WIRES
- LIMIT OF TRAVELED WAY

**Notes**

Revision	By	Appd.	YY.MM.DD

Orland Village Dam Alternatives Study	DWH	MRC	13.03.11
Issued	By	Appd.	YY.MM.DD

File Name:	Dwn.	Chkd.	Dsgn.	YY.MM.DD
------------	------	-------	-------	----------

**Permit-Seal**

**Client/Project**

TOWN OF ORLAND  
 ORLAND VILLAGE DAM  
 ALTERNATIVES FEASIBILITY STUDY  
 Orland, Maine

**Title**

PROJECT ALTERNATIVE B -  
 DAM & FISHWAY MAINTENANCE


Project No. 195600824	Scale 1" = 20'
Drawing No.	Sheet
	Revision

EXISTING FISHPASS  
 (TO BE REPAIRED  
 AND MAINTAINED)

TIMBER-CRIB  
 SPILLWAY SECTION  
 (TO BE MAINTAINED)

NARRAMISIC RIVER  
 (NON-TIDAL)

ORLAND RIVER  
 (TIDAL)



**DRAFT**  
**NOT FOR CONSTRUCTION**  
 MARCH 11, 2013